



State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program Date May 24, 2010

Reviewed:	PBRY
Br Tallet 115	-

Permit Number: S/039/0027

Inspection Date: April 15,2010

Inspector(s): John Rogers and Paul Baker	ohn Rogers and Paul Baker Time: 10:30 AM – 12:00 PM		
Other Participants: none	Mine Status: active		
Elements of Inspection	Evaluated	Comment	Enforcemen
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)	$\overline{\boxtimes}$	$\overline{\boxtimes}$	
3. Protection of Drainages / Erosion Control			
4. Deleterious Material	$\overline{\boxtimes}$	$\overline{\boxtimes}$	
5. Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation	$\overline{\boxtimes}$	$\overline{\boxtimes}$	
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)			
8. Soils			
9. Revegetation			

Bond Amount: \$0.00 - no permit

Mine Name: Todd Wilhite - Mt. Pleasant

Operator Name: Todd Wilhite

Purpose of Inspection: The Division had been notified that Todd Wilhite was operating a stone quarry East of Mt. Pleasant with out a mining permit. The purpose of the inspection was to verify this and if confirmed, write a cessation order (CO)

Inspection Summary:

There was an operating stone quarry with a GPS area of 17 acres. It was GPS during the inspection. After about an hour, a driver show up to pick up stone. It was confirmed with him that the quarry was being operated by Todd Wilhite. He telephoned Mr. Wilhite and informed him of our presence and the CO. We did not talk to Mr. Wilhite. A cessation order (MC2010-41-1) was given to the driver, but he refuse to sign it.

The quarry comprised several small (15–50 ft diameter) exploration pits and trenches 3-5 feet deep scattered across the area searching for landscape rock (2-3 ft. in diameter). There was no central pit. The equipment on site consisted of two large track hoes and a front-end loader. There was trash and deleterious material scattered about the area. Pictures were taken (4/15/2010) to document the current conditions.

Conclusions and Recommendations:

Mr. Wilhite must immediately stopped mining and either get:

- 1. An approved mining permit with a surety bond and reclamation contract, OR
- 2 Begin reclamation immediately of the area and post a \$5000 bond for the revegtation of the area.

He will be given until May 15, 2010 to comply with CO.

Inspection Date: April 15, 2010

Page 2 of 5 S/039/0027

Secondary Note: A follow up inspection on May 3, 2010 showed that the area had been almost completely regraded. Pictures were taken (5/3/2010) to document the reclamation process. Therefore, with the positive effort by Mr. Wilhite, he was given an extension until June 8, 2010 to post his revegetation bond of \$5000 bond OR get an approved mining permit, surety bond and reclamation contract so that he may continue mining.

Inspector's Signature

JCR: vs

Todd Wihite - operator







